

IMPORTANT SAFETY RECALL

MiniMax NT STD Pool Heaters

Pentair Water Pool and Spa, Inc. is recalling certain MiniMax NT STD Pool Heaters to inspect and repair. Some heaters may emit excess carbon monoxide, which could result in severe personal injury in the event of a vent leak in an indoor or fully enclosed installation.

This repair program is being conducted for heaters **installed indoors or fully enclosed** with the following model numbers:

Model Number	BTU	Fuel	Model Number	BTU	Fuel
460534	200,000	Natural Gas	460532	300,000	Natural Gas
460563	200,000	Natural Gas	460551	300,000	Natural Gas
460427	200,000	Natural Gas	460429	300,000	Natural Gas
460561	200,000	Natural Gas	460549	300,000	Natural Gas
460565	200,000	Natural Gas	460553	300,000	Natural Gas
460447	200,000	Natural Gas	460449	300,000	Natural Gas
460538	200,000	Propane	460536	300,000	Propane
460564	200,000	Propane	460552	300,000	Propane
460439	200,000	Propane	460441	300,000	Propane
460562	200,000	Propane	460550	300,000	Propane
460566	200,000	Propane	460554	300,000	Propane
460443	200,000	Propane	460445	300,000	Propane
460533	250,000	Natural Gas	460531	400,000	Natural Gas
460557	250,000	Natural Gas	460545	400,000	Natural Gas
460428	250,000	Natural Gas	460430	400,000	Natural Gas
460555	250,000	Natural Gas	460543	400,000	Natural Gas
460559	250,000	Natural Gas	460547	400,000	Natural Gas
460448	250,000	Natural Gas	460450	400,000	Natural Gas
460537	250,000	Propane	460535	400,000	Propane
460558	250,000	Propane	460546	400,000	Propane
460440	250,000	Propane	460442	400,000	Propane
460556	250,000	Propane	460544	400,000	Propane
460560	250,000	Propane	460548	400,000	Propane
460444	250,000	Propane	460446	400,000	Propane

Units with serial numbers beginning with 0606003 and higher are not affected.



If your heater is affected, **STOP USING IT IMMEDIATELY**, and call Pentair, toll free at 1-866-761-5272 between 8:00 a.m. and 6:00 p.m., Eastern Time, Monday through Friday to arrange for a free inspection and free repair, if necessary.